

AREPAs reference list of marine and offshore tasks

Reference	Type	Year	Location	Damage	AREPA's effort
M/F Kanhave	Ferry	2009	Hov, Denmark	Fire	Analysis and advising
Tor Ficaria	Ferry	2009	Bremerhaven, Germany	Fire	Analysis and advising
Maersk Resolute	Jackuprig	2009	The North Sea	Dust	Restoration
Newfound Pioneer	Trawler	2009	Frederikshavn, Denmark	Fire	Analysis and advising
Maersk Galant		2009	Silkeborg, Denmark		Decontamination of 46 PCBs
Under construction - L 217, Maas Viking	Ro/Ro	2009	Odense, Denmark	Fire	Analyses and advising
Ocean Sky	AH-Tug/Standby/Supply vessel	2009	Kristiansund, Norway	Fire	Analysis, advising and restoration
Under construction - L 216	Container ship	2009	Odense, Denmark	Fire	Analysis and advising
Falkur	Trawler	2008	Runavik, Faroe Islands	Fire	Analysis and advising
Maersk Master	Anchor handling tug support vessel	2008	Brazil	Fire	Analysis and advising
British Innovator	Carrier	2008	Ferrol, Spain	Dust	Restoration
Normandy	Ferry	2008	Fredericia, Demark	Fire	Analysis, advising and restoration
Avance	Backhoe hopper dredger	2008	Løgstør, Denmark	Fire	Analysis and advising
M/V Carola	Cargo ship	2008	Aarhus, Denmark	Fire	Analysis and advising
M/T Olivia	Tanker	2008	Las Palmas, Gran Canaria	Fire	Analysis and advising
M/V Alexander Maersk	Feeder	2008	Dakar, Senegal	Fire	Analysis and advising
Green Selje	Cargo ship	2008	Gothenburg, Sweden	Fire	Analysis, advising and restoration
British Merchant	Carrier	2008	Fene, Spain	Dust	Restoration
Under construction - L 214	Container ship	2008	Odense, Denmark	Fire	Analysis and advising
MT EK-river	Tanker	2008	Gothenburg, Sweden	Fire	Analysis, advising and restoration
Maersk Guardian	Platform	2008	Silkeborg, Denmark	Fire	Analysis and advising
Safmarine Onne	Dry cargo vessel	2008	Dakar, Senegal	Fire	Analysis and advising
M.S.C. "Suez"	Container carrier	2007	Adelaide, Australia	Fire	Analysis and advising
M/T Tina Jakobsen	Tanker	2007	Skagen, Denmark	Fire	Analysis, advising and restoration
M/T Rikke Theresa	Tanker	2007	Istanbul, Turkey	Fire	Analysis and advising
Ekko	Surveying vessel	2007	Thyborøn and Silkeborg, Denmark	Extinguishants	Analysis, advising and restoration
M/V Sarfaq Ittuk	Liner	2007	Aalborg, Denmark	Salt water	Advising and restoration
M/S Peter Wessel	Ferry	2007	Frederikshavn, Denmark	Fire	Analysis, advising and restoration
Tycho Brahe	Ferry	2007	Helsingborg, Sweden	Fire	Analysis, advising and restoration
M/S Prinsesse Ragnhild	Ferry	2007	Frederikshavn, Denmark	Fire	Analysis and advising
Svend Åge	Collier	2007	Skødstrup, Denmark	Water	Restoration
Hercules	Trawler	2007	Penco, Chile	Fire	Analysis and advising
SIF R	Hopper dredger	2007	Fredericia, Denmark	Fire	Analysis and advising
CSO Wellservicer	Diver vessel	2007	Stavanger, Norway	Fire	Analysis and advising
LIFISK-Bergen	Trawler	2007	Hirtshals, Denmark	Fire	Analysis and advising
Athena	Trawler	2007	Penco, Chile	Fire	Analysis and advising

Reference	Type	Year	Location	Damage	AREPA's effort
Brage R	Dredger	2007	Thyborøn, Denmark	Fire	Analysis, advising and restoration
Eline	Container ship	2007	Grenaa, Denmark	Salt water	Advising
Nordskott	Ro/Ro	2007	Harstad, Norway	Fire	Analysis, advising and restoration
Under construction - L 209	Container ship	2007	Odense, Denmark	Fire	Analysis and advising
Centurion del Atlantico	Trawler	2007	Frederikshavn, Denmark	Fire	Analysis and advising
Pride of Telemark	Ferry	2007	Hirtshals, Denmark	Salt water	Analysis, advising and restoration
Halfdan	Platform	2007	The North Sea	Fire	Analysis, advising and restoration
HE 1 (new construction)	Platform	2007	Singapore	Fire	Analysis and advising
Magnus Heinason	Fishery protection vessel	2007	Tórshavn, Faroe Islands	Fire	Analysis, advising and restoration
Esvagt Carina	Standby/Rescue	2007	Esbjerg, Denmark	Fire	Analysis and advising
Lygra	Carrier	2007	Esbjerg, Denmark	Fire	Analysis, advising and restoration
L 428 Bounty	Trawler	2007	Thyborøn, Denmark	Salt water	Analysis, advising and restoration
New building Jiangnan 2342	Chemical tanker	2007	Shanghai, China	Fire	Analysis, advising and restoration
Sea-Land Integrity	Container ship	2007	Lisbon, Portugal	Fire	Analysis and advising
EIF 400 No.1, reg. no. P570 (new construction)	Inspection vessel	2007	Skagen, Denmark	Fire	Analysis and advising
M/S Vertigo	Bulk carrier	2006	Fredericia, Denmark	Salt water	Cleaning
Stelkur FD 1202	Trawler	2006	The Faroe Islands	Fire	Analysis and advising
Esvagt Omega	Supply vessel	2006	Esbjerg, Denmark	Fire	Analysis and advising
M/S Karina Munk	Fishing vessel	2006	Thyborøn, Denmark	Fire	Analysis and advising
M/V Blue Castor	Supply vessel	2006	Sokhna, Egypt	Fire	Analysis, advising and restoration
L56 Anne Lise	Fishing vessel	2006	Thyborøn, Denmark	Fire	Analysis, advising and restoration
M/V MSC Nuria	Container ship	2006	Barcelona, Spain	Fire	Analysis and advising
Nicolaj Saj	Survey ship	2006	Silkeborg, Denmark	Water	Restoration
Gudmundur VE 29	Fishing vessel	2006	Gdynia, Poland	Fire	Analysis, consultancy and supervision of restoration by others
New construction L203	Container ship	2006	Odense, Denmark	Fire and salt water	Analysis, advising and restoration
Nanoq Trawl	Trawler	2006	Hirtshals and Frederikshavn, Denmark	Fire	Analysis and advising
M/T Sigas Eildon	Tanker	2006	La Coruna, Spain + Frederikshavn, Denmark	Fire	Analysis, advising and restoration
Esvagt Omega	Supply vessel	2006	Esbjerg, Denmark	Fire	Analysis, advising and restoration
M/V Havborg af Leirvik	Trawler	2006	Runavik, Faroe Islands	Fire	Analysis, advising and restoration
M/V Tina Jakobsen	Tanker	2006	Vlaardingen, Holland	Fire	Analysis, advising, restoration and supervision
M/V Ice Flake	Refrigerator ship	2006	Durban, South Africa	Fire	Analysis and advising
M/V Frigga	Tug boat	2006	Fredericia, Denmark	Fire	Analysis, advising and restoration
	Components from a Bayliner 205	2006	Silkeborg, Denmark	Salt water	Advising
HG 276 Pernille Thomas	Trawler	2006	Hirtshals, Denmark	Fire	Analysis and advising
M/V Sally	Bulk carrier	2005	Riga, Latvia	Fire	Analysis and advising
M/T Olivia	Tanker	2005	Køge and Frederikshavn, Denmark	Fire	Analysis, advising and restoration
MSF 3	Naval vessel	2005	Frederikshavn, Denmark	Fire	Analysis and advising
M/V Corner Brook	Side-loading pallet carrier	2005	Tilbury, England	Fire	Analysis and advising

Reference	Type	Year	Location	Damage	AREPA's effort
M/V Aniara	Car carrier	2005	Piraeus, Greece	Fire	Analysis, advising and restoration
Dan FG	Platform	2005	Offshore	Dust	3 x restoration
M/S Sudringur T600	Trawler	2005	Runavik, The Faroe Islands	Fire	Analysis and advising
M/S Esvagt Charlie	Standby/Rescue vessel	2005	Esbjerg, Denmark	Fire	Analysis, advising and restoration
M/F Stena Saga	Ferry	2005	Frederikshavn, Denmark	Fire	Analysis, advising and restoration
Sigloo Hav	Tanker	2005	Dubai, United Arab Emirates	Fire	Analysis, advising and restoration
Tyra East	Platform	2005	Offshore	Salt water	Advising and restoration
M/F Maersk Dunkerque	Ferry	2005	Geoje, Korea	Fire	Analysis and advising
East Express	Container ship	2005	Cadiz, Spain	Fire	Analysis, advising and restoration
M/S Havgus	Diving ship	2005	Grenaa, Denmark	Fire	Analysis and advising
M/S Tor Anglia	Roll-on/roll-off ship	2005	Dubai, United Arab Emirates	Fire	Analysis and advising
Skandi Hav	Platform ship	2005	Frederikshavn, Denmark	Maintenance	Cleaning
M/T Panam Serena	Chemical tanker	2004	Port Torres, Sardinia	Explosion	Data reconstruction, analysis and advising
Pride of America	Cruise ship	2004	Bremerhaven, Germany	Water	Advising
M/S Rocknes	Bulk carrier	2004	Stavanger, Norway	Water	Advising
Maria Nymann	Fishing-vessel	2004	Esbjerg, Denmark	Fire	Analysis, advising and restoration
Pia Pedersen	Fishing-vessel	2004	Esbjerg, Denmark	Fire	Analysis and advising
Sebber	Sailing boat	2004	Struer, Denmark	Fire	Analysis, advising and restoration
Lipton	Fishing-vessel	2004	Grenaa, Denmark	Fire	Analysis and advising
M/T Neptunus	Tanker	2004	Fredericia, Denmark	Fire	Analysis, advising and restoration
Marilee	Tanker	2004	Jeddah	Water	Advising and restoration
Esvagt Supporter	Standby/rescue vessel	2004	Frederikshavn, Denmark	Fire	Analysis and advising
Sonja Doris	Trawler	2004	Esbjerg, Denmark	Fire	Analysis and advising
Thor R	Dredger	2004	Esbjerg, Denmark	Water	Advising and restoration
Darwin E 689	Fishing-vessel	2004	Esbjerg, Denmark	Fire	Analysis and advising
Northern Seeker	Supply vessel	2004	Esbjerg, Denmark	Fire	Analysis, advising and restoration
Regnar, Dan Feltet	Buoy	2003	Offshore	Oil/soot	Advising and restoration
M/V Maersk Terrier	Supply boat	2003	Singapore	Water	Advising and restoration
Prinsesse Ragnhild		2003	Norway	Fire	Restoration
Silja Martine E 147	Fishing-vessel	2003	Aabenraa, Denmark	Fire	Analysis, advising and restoration
M/S Charlotte	Fishing-vessel	2003	Juelsminde, Denmark	Fire	Analysis, advising and restoration
M/S Sarfaq Ittuk	Liner	2003	Iceland	Water	Advising
M/S Skandi Fjord	Supply boat	2003	Esbjerg, Denmark	Fire	Restoration
M/V Petersborg	Ferry	2003	Rostock, Germany	Fire	Analysis and advising
M/V Hanne Danica	Coaster	2003	Yemen, Constanta and Istanbul	Fire	Analysis, advising and restoration
HF Villum Clausen	Ferry	2003	Ystad, Sweden	Fire	Analysis and advising
Matvik	Tanker	2003	Fredericia, Denmark	Fire	Analysis and advising
M/V Ice Rose	Refrigerator ship	2003	Aarhus, Denmark	Fire	Analysis, advising and restoration
M/S Dana Sirena	Ferry	2003	Esbjerg, Denmark	Water	Advising

Reference	Type	Year	Location	Damage	AREPA's effort
DSDN Pelican		2003	Esbjerg, Denmark		Advising
M/S Povl Anker	Ferry	2002	Rønne, Denmark	Fire	Analysis and advising
Fjøllguten II		2002	Norway	Water	Restoration
M/V Maersk Wave	Ro/Ro	2002	Bremerhaven, Germany	Fire	Analysis, advising and restoration
M/T Sunny Blossom	Tanker	2002	Algeciras, Spain	Fire	Analysis, advising and restoration
Maersk Enhancer		2002	England	Fire	Analysis
M/S Knock Sally		2002	West India	Water	Restoration
M/S Regulus	Cargo ship	2002	Taranto, Italy	Fire	Analysis, advising and restoration
M/F Princess of Scandinavia	Ferry	2002	Kristianssand, Norway	Fire	Analysis and advising
Tælavåg	Fishing-vessel	2002	Hanstholm, Denmark	Fire	Analysis and advising
M/S Nordskott	Ro/Ro	2002	Frederikshavn, Denmark	Fire	Analysis, advising and restoration
M.V. Lia	Tanker	2002	Salvadore, Brazil	Fire	Analysis and advising
M/V Clare	Ro/Ro	2002	Scotland	Water	Advising and restoration
Beltannia	Rebuilt pilot boat	2002	Esbjerg, Denmark	Fire	Analysis and advising
M/S Arkona, Thyborøn	Cruise ship	2002	Thyborøn, Denmark	Fire	Analysis, advising and restoration
Maersk Winner	Supply boat	2002	Stralsund, Germany	Fire	Analysis and advising
Ramform Valiant		2002	Spain/Africa	Water	Restoration
M/S Marie Therese	Tanker	2001	Le Havre, France	Fire	Analysis, advising and restoration
Pearl of Scandinavia	Cruise ship	2001	Aalborg, Denmark	Fire	Analysis and advising
Forest Interprise	Cargo vessel	2001	Panama, Equador	Water	Advising and restoration
M/S Marie Therese	Tanker	2001	Le Havre, France	Fire	Analysis after fire in engine room
Olympic Supplier	Supply boat	2001	Ølen, Norway	Fire	Analysis after fire in engine room
M/F SASSNITS	Ferry	2001	Sassnits, Deutschland	Fire	Analysis, advising and restoration
M/V Marshall Bagramyan	Tanker	2001	Nantong, China	Fire	Analysis and advising
M/S Fure Star	Tanker	2001	Frederikshavn, Denmark	Fire	Analysis, advising and restoration
M/S Scandi Navica	Subsea cable ship	2001	Esbjerg, Denmark	Fire	Analysis, advising and restoration
M/S Enalios Skiron	Tanker	2001	Rilica, Croatia	Fire	Analysis after fire in engine room
Methane Polar	Tanker	2001	Piraeus, Greece	Water	Analysis and advising
Bolette Munkholm	Trawler	2001	Hvide Sande, Denmark	Water	Advising and restoration
M/V Bov Viking	Tanker	2001	Suez, Egypt	Fire	Analysis and advising
M/S Borga		2001	Norway	Water	Restoration
Åsgård B	Gas prod. platform	2000	The North Sea	Dust	Restoration
M/S Heimdahl	Ferry	2000	Frederikshavn, Denmark	Fire	Analysis and advising
New construction GMDS 1	Floating oil drilling rig	2000	Belfast, Ireland	Water	Analysis and advising
Åsgård B	Gas prod. platform	2000	Stavanger, Norway	Fire	Analysis
M/S Anne Lise Poulsen	Fishing vessel	2000	Thyborøn, Denmark	Fire	Analysis and advising
S158 Danit of Skagen	Fishing vessel	2000	Skagen, Denmark	Fire	Analysis, advising and restoration
M/S E202 Torino	Trawler	2000	Esbjerg, Denmark	Fire	Analysis, advising and restoration
Esvagt Preserver	Standby/rescue vessel	2000	Esbjerg, Denmark	Fire	Analysis, advising and restoration

Reference	Type	Year	Location	Damage	AREPA's effort
Northern Access	Research vessel	2000	Oresund, Sweden	Fire	Advising and co-ordination
Sleipner	Ferry	2000	Stord, Norway	Water	Reconstruction of data after 4 months on the seabed
M/T SITAKATRINE	Product carrier	2000	Singapore	Fire	Analysis, advising and restoration
M/S Sovereign Maersk	Container vessel	2000	Kobe, Japan	Fire	Analysis, advising and restoration after explosion
M/S Maersk Topper	Supply boat	2000	Rio de Janeiro, Brazil	Fire	Analysis, advising, restoration and co-ordination
M/S Haugan		2000	Norway	Fire	Analysis
Springeren	Submarine	2000	Frederikshavn + Aarhus, Denmark	Fire	Analysis and advising
Najaarac	Ferry	2000	Narsaq, Greenland	Fire	Analysis, advising and restoration
Maersk Chancellor	Supply boat	2000	Trinidad	Fire	Analysis, advising and restoration
M/S Lolita		2000	Norway	Fire	Restoration
FGSO NKOSSA II	Gas prod. vessel	2000	Point Noire, Congo	Fire	Analysis, advising and restoration
M/S Svanavåg		2000	Norway	Fire	Restoration
Ærø-færgen	Ferry	2000	Ærø, Denmark	Fire	Analysis, advising and restoration
Snorre B	Oil rig	2000	Cadiz, Spain	Dust	Restoration after dust contamination on electronics
	Ro/Ro	2000	Gothenburg, Sweden	Fire	Analysis and restoration
M/S Biostar		2000	Norway	Fire	Restoration
Inger Hildur	Fishing trawler	1999	Egersund, Norway	Fire	Restoration
Troll C	Gas prod. platform	1999	Haugesund, Norway	Fire	Analysis and restoration
M/S Sveanor	Cargo boat	1999	Arendal, Norway	Fire	Restoration
M/S Gardar	Trawler	1999	Stavanger, Norway	Fire	Analysis
New construction 166	Container vessel	1999	Odense, Denmark	Fire	Analysis and advising
M/Y D'Angleterre II	Yacht	1999	Genoa, Italy	Fire	Analysis, advising and restoration
M/S Maersk Server	Supply boat	1999	Point Noire, Congo	Fire	Analysis, advising and restoration
Noble Piet van Ede	Rig	1999	The North Sea	Fire	Analysis, advising, restoration and co-ordination
M/S Ocean Flower	Supply boat	1999	Eggesund, Norway		
M/S Tor Selandia	Ro/Ro	1999	Gothenburg, Sweden	Water	Analysis, advising and co-ordination
M/S Skaane	Ferry	1999	Trelleborg, Sweden	Fire	Analysis, advising and restoration of switchboards
DFDS Flandria	Ro/Ro	1999	Gothenburg, Sweden	Water	Advising and supervision
L495 Diamant	Trawler	1999	Thyborøn, Denmark	Fire	Analysis, advising and restoration
Thetis	Protection vessel	1999	Frederikshavn, Denmark	Fire	Analysis, advising and restoration
M/S Povl Anker	Ferry	1999	Fredericia, Denmark	Oil pollution	Advising and restoration
	Crane	1999	Esbjerg, Denmark	Water	Advising and co-ordination
Åsgård B	Gas prod. platform	1999	Stavanger, Norway	Dust	Restoration of electronics
Åsgård B	Gas prod. platform	1999	The North Sea	Dust	Analysis
Prinsesse Ragnhild	Cruise ship	1999	Gothenburg, Sweden		
Scandi Navica	Subsea cable ship	1999	Ålesund, Norway	Dust	Analysis and restoration
Royal Greenland	Factory ship	1999	Frederikshavn, Denmark	Fire	Analysis, advising and restoration
PD 120	Trawler	1999	Skagen, Denmark	Water	Advising and restoration
Åsgård B	Gas prod. platform	1999	The North Sea	Smoke	Analysis

Reference	Type	Year	Location	Damage	AREPA's effort
Entebber	Oil drilling rig	1999	Esbjerg, Denmark	Salt pollution	Restoration
New construction 170	Container vessel	1999	Odense, Denmark	Fire	Analysis and advising
DFDS Flandria		1998	Gothenburg, Sweden		
M/S Bravur	Tanker	1998	Copenhagen + Marstal, Denmark	Fire	Analysis, advising and restoration
Freja R	Dredger	1998	Thyborøn, Denmark	Fire	Analysis, advising and restoration
SO709 MS Brendelen	Trawler	1998	Skagen, Denmark	Fire	Analysis, advising and restoration
Morten Stage	Lifeboat	1998	Aalborg, Denmark	Water	Analysis, advising and restoration
L847 M/S Pia Peter	Fishing vessel	1998	Thyborøn, Denmark	Fire	Analysis, advising and restoration
M/S Kronborg	Ferry	1998	Fredericia, Denmark	Fire	Analysis, advising and restoration
M/T Lotus	Tanker	1998	Tjøemme, Norway	Fire	Restoration
M/T Tiny Swan	Tanker	1998	Fredericia, Denmark	Fire	Analysis and advising
M/S Kukawa	Container vessel	1998	Falmouth, Cornwall, UK	Fire	Analysis, advising, restoration and co-ordination
Monte d'oro	Ferry	1998	Marseille + Bastia, France	Fire	Analysis, advising, restoration and co-ordination
Petsamo		1998	Aarhus, Denmark	Water	Advising and restoration
Henry	Dredger	1998	Aarhus, Denmark	Water	Analysis, advising and restoration
MSV Baltica		1998	Florø, Norway	Dust	Analysis, advising and restoration
Poly Concord	Hotel rig	1998	Haugesund, Norway	Fire	Analysis and restoration of electrical switchgears
Diamant	Trawler	1998	Hirtshals, Denmark	Fire	Analysis and restoration
Åsgård A	Oil prod. ship	1998	The North Sea	Water	Restoration
Union Titan		1997	Rotterdam, Netherlands		
M/S Gerda Maria	Trawler	1997	Bremen, Germany		
M/S Maersk Skipper	Supply vessel	1997	Fredericia, Denmark	Fire	Analysis and advising
M/S Bestla Svitzer	Tug boat	1997	Fredericia, Denmark	Fire	Analysis and advising
New construction 733	Tanker	1997	Frederikshavn, Denmark	Fire	Analysis, advising and restoration
M/S Western Patriot	Seismic vessel	1997	Aarhus, Denmark	Oil pollution	Analysis and advising
New construction L160	Container vessel	1997	Odense, Denmark	Fire	Analysis, advising and restoration
M/V Pioneer Louise	Gas tanker	1997	The Gulf, United Arab Emirates	Fire	Analysis, advising, restoration and co-ordination
Harald	Platform	1997	Esbjerg, Denmark	Water	Restoration
Maren	Environmental boat	1997	Randers, Denmark	Water	Advising and restoration
M/S Multitank Armenia	Chemical tanker	1997	Rotterdam, Netherlands	Fire	Analysis, advising, restoration and co-ordination
M/S Jane Viking	Supply vessel	1997	Grimstad, Norway	Fire	Analysis, advising and restoration
Mercuri	Cruise liner	1997	Bremen, Germany	Fire	Analysis and advising
Tridens 1	Research vessel	1997	Stavanger, Norway	Fire	Restoration
	Tug Vessel	1997	Great Belt, Denmark	Water	Analysis and restoration of communication equipment
M/S Saga Rose	Cruise ship	1997	Southampton, UK	Fire	Analysis, advising, restoration and co-ordination
Sleipner		1997	Norway	Water	Recovery of data
M/S Napoleon	Ferry	1996	Marseille, France		
M/S Bristol	Trawler	1996	Aalborg, Denmark		
M/S Stold Confidence		1996	Aalborg, Denmark		

Reference	Type	Year	Location	Damage	AREPA's effort
Sand Kirk	Trawler	1996	Esbjerg, Denmark		
Polar Search	Research vessel	1996	Aarhus, Denmark		
Under construction	Trawler	1996	Frederikshavn, Denmark		
Stena Frighter	Ro/Ro	1996	Fredericia, Denmark		
Gorm	Platform	1996	Gormfield, North Sea		
DFDS Winston Churchill	Ferry	1996	Esbjerg, Denmark		
Scombus	Trawler	1995	Amsterdam, Netherlands		
M/S Dana Hafnia	Ferry	1995	Esbjerg, Denmark		
M/S VasiliyGolovnin	Fishing ship	1995	Pusan, Korea		
Erikson Crystal	Freeze ship	1995	Rotterdam, Netherlands		
ULA Q	Platform	1995	The North Sea		
DFDS Tor Hollandia	Container ship	1995	Rotterdam, Netherlands, and Esbjerg, Denmark		
Heidrun	Oil rig	1995	Stavanger, Norway		
M/S Dana Hafnia	Ferry	1995	Copenhagen, Denmark		
Under construction	Diving supply ship	1995	Aarhus, Denmark		
Maersk Trader	Supply boat	1995	Rotterdam, Netherlands		
Longva III	Trawler	1994	Christchurch, New Zealand		
M/S Traenen	Coast streamer	1994	Volda		
F/W Venus	Trawler	1994	Iceland		
M/V Rautaruuki	Bulk carrier	1994	Riga		
Gyda	Platform	1994	The North Sea		
Niels Juul	Corvette	1994	Korsør, Denmark		
M/F Prinsesse Anne-Marie	Ferry	1994	Hundested, Denmark		
F/V Veronica	Trawler	1993	Norway		
Erikson Crystal	Freeze ship	1993	Las Palmas		
Skagerak	Cable streamer	1993	Krisland, Norway		
Queen of Scandinavia	Ferry	1993	Esbjerg, Denmark		
Maersk Terrier	Supply vessel	1993	Aberdeen, Scotland, and Fredericia, Denmark		
M/S Nesborg	Trawler	1993	The Faroe Islands		
Ladby Maersk	Container ship	1993	Gothenburg, Sweden		
F/K Simrad	Research vessel	1992	Horten, Norway		
T/S Klorina	Tug boat	1992	Langøya, Norway		
M/TR Malina	Trawler	1992	Greenland		
M/S Kalliopi T	Bulk carrier	1991	Gothenburg, Sweden		
Barge DLB 801	Barge	1986	Sharjar, United Arab Emirates		
Anders Maersk	Container ship	1985	Rotterdam, Netherlands		
Maersk Gabarus	Supply vessel	2004/2005	Halifax, Canada	Water, fire and powder	Analysis, advising and restoration